

Power Stock

2016 Crate Motor Rules

602 GM Crate Motor

- **1.** Must be purchased NEW from a GM dealer. Furlong Chevrolet in Northfield or Suburban Chevrolet in Eden Prairie are recommended.
- 2. **IMPORTANT:** Motors may NOT be rebuilt or repaired.
- **3.** Inspection plug in the oil pan is mandatory. **Only** Murgic's Auto is authorize to perform this work and will reseal the pan with their seals.
- **4.** Exhaust and carburetor rules are the same as 2015.
- 5. Mr. Gasket carburetor adapter, part #1932, must be used with a Quadra-jet carburetor.
- 6. Upper and lower adapter gaskets may be up to .065" thick each.
- 7. MSD Soft Touch rev control, part #8727CT must be used. Max 6400 RPM.
- 8. Pump premium fuel only. NO RACE FUEL.
- 9. 100 pound weight break with a Crate Motor. Percentages will remain the same.
- 10. Valve spring and rocker arms may be replaced as maintenance items, and must be GM OEM per 'Circle Track Crate Engine Technical Manual'.
- 11. Parts list Retail prices:
 - a. Mr. Gasket Carb Adapter. Part #1932 \$17.99
 - b. MSD Soft Touch Rev Control. Part #8727CT \$157.95
 - c. External balance Flex-plate required.
 - d. R&R Oil Pan Install Inspection Plug \$200.00



Thunder Car 2016 Crate Motor Rules

602 GM Crate Motor

- 1. Must be purchased NEW from a GM dealer. Furlong Chevrolet in Northfield or Suburban Chevrolet in Eden Prairie are recommended.
- 2. **IMPORTANT:** Motors may NOT be rebuilt or repaired.
- **3.** Inspection plug in the oil pan is mandatory. **Only** Murgic's Auto is authorize to perform this work and will reseal the pan with their seals.
- 4. MSD Soft Touch rev control, part #8727CT must be used. Max 6400 RPM.
- 5. Pump premium fuel only. NO RACE FUEL.
- 6. 100 pound weight break with a Crate Motor. Percentages will remain the same.
- 7. Valve spring and rocker arms may be replaced as maintenance items, and must be GM OEM per 'Circle Track Crate Engine Technical Manual'.
- 8. Holley 650HP series 4150, part #80541-1 only.
 - a. Must be as manufactured.
 - b. Re-jetting is allowed.
 - c. All parts must be Holley OEM.
- 9. One carb base gasket max .250" thick. NO spacer plates allowed.
- 10. Schoenfield headers, part #135 or #145 only.
- 11. Parts list Retail prices:
 - a. MSD Soft Touch Rev Control. Part #8727CT \$157.95
 - b. External balance Flex-plate required.
 - c. Schoenfield headers. Part #135 or #145 \$250.00
 - **d.** Holley 650HP carb. Part # 80541-1 \$800.00
 - e. R&R Oil Pan Install Inspection Plug \$200.00